



DysonAnalysis.com
6279 CR 1140

Celeste, Texas 75423

1255001

0725

Sample Information
 Site: Celeste, TX
 Area: Norman Tan Souza
 Unit: Honda
 Equipment: Gasoline Engine
 Description: S2000 2.2L
 Sample Pt Key
 Fluid in Use: Motul 300V 5w40
 Fluid Grade: SAE CRANKCASE 5w40
 Lst Fluid Change

Equipment Information
 Equipment Type: Gasoline Engine
 Cooled: Cooling Source
 Filtered: Filter Size
 Lst Filter Change
 Sump Capacity
 Lubrication System
 Lubed Components
 Bearing Types
 Gear Types

Sample Evaluation

Wear Physical Contaminant Lab

Sample Information		Wear Metals					Additive Metals					Contaminant Metals													
Samp No	Hrs/Miles	Samp Date	Iron	Copper	Tin	Lead	Chrom	Nickel	Alum	Titan	Silver	Calcium	Magne	Zinc	Phos	Barium	Molyb	Antim	Silico	Sodium	Boron	Potas	Vanad		
09080580	9000/55000	08/10/2009	22	10	8	8	1	0	9	0	0	1276	1196	1236	1216	6	784	0	11	10	1	0	0		
Watch Advisory			50	25	20	25	15	10	15	10	10														
Warning Advisory			100	50	40	50	30	20	30	20	20														
Reference																									

Physical and Other Tests

Sample Information	V40C	V100C	TAN	FLASH	OXID	NIT	KF	TBN	FUEL	SOOT	GLYCOL	vndx
09080580 08/10/2009	81.2	14.6	0.47	330	186	17	1722	6.1	1.20	0.04	0	190
Watch	135	-165	2.5	400	20	15	750	3	2	2		
Warning	127.5-172.5	12.2-16.6	4	375	30	25	1500	4	4	4		
Ref												

Other Tests

Sample No Comments / Recommendations

09080580 08/10/2009	09080580	Sulfate By Product = 161.
---------------------	----------	---------------------------

Watch
Warning
Ref

PHONE: 903.413.2071

EMAIL: terry@dysonanalysis.com