



DysonAnalysis.com
6279 CR 1140

Celeste, Texas 75423

1255001

Sample Information
 Site Celeste, TX 0726
 Area Norman Tan Souza
 Unit Honda
 Equipment Gearbox
 Description S2000 2.2L 6 spd
 Sample Pt Key Motul Gear 300 75w90
 Fluid in Use SAE GEAR OIL 75w90
 Fluid Grade
 Lst Fluid Change

Equipment Information
 Equipment Type Gasoline Engine
 Cooled Cooling Source
 Filtered Filter Size
 Lst Filter Change
 Sump Capacity
 Lubrication System
 Lubed Components
 Bearing Types
 Gear Types

Sample Evaluation

Wear **Physical** **Contaminant** **Lab**

Sample Information		Wear Metals				Additive Metals				Contaminant Metals													
Samp No	Hrs/Miles	Samp Date	Iron	Coppe	Tin	Lead	Chrom	Nickel	Alum	Titan	Silver	Calcium	Magne	Zinc	Phos	Barium	Molyb	Antim	Silico	Sodium	Boron	Potas	Vanad
09080581	9000/55000	08/10/2009	34	5	0	0	1	0	1	0	0	22	711	19	1703	0	1	0	13	3	439	0	0
			50	25	20	25	15	10	15	10	10								20	150	50	25	10
			100	50	40	50	30	20	30	20	20								75	150	100	50	20

Watch Advisory
 Warning Advisory
 Reference

Physical and Other Tests

Sample Information	V40C	V100C	TAN	FLASH	OXID	NIT	KF	TBN	FUEL	SOOT	GLYCOL	vndx
09080581 08/10/2009	86.9	14.6	1.76	310	165	7	1569	1.7	1.38	0.03	0	177
Watch Warning Ref			2.5	400	20	15	750	3	2	2		
			4	375	30	25	1500		4	4		

Other Tests

Sample Information	Samp No	Comments / Recommendations
09080581 08/10/2009	09080581	Sulfate By Product = 119.

Watch
 Warning
 Ref

PHONE: 903.413.2071

EMAIL: terry@dysonanalysis.com